

High Power Shot Peener: **(Preparation work)**

Air Pressure : min. 75 PSI / 5 bar

Connection: 3/4"

Space required from the left belt edge: 8"

Space required from the right Belt edge: 8"

Approx. Duration:	Set up	3 hrs.
	Dismantling	3 hrs.

Recommended belt speed: 10 m per min

